UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

Page 1 of 2

PATENT NO.

: 6,922,628 B2

DATED

: July 26, 2005

INVENTOR(S) : Guoming G. Zhu et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1,

Line 54, "diagnostic" should be -- diagnostics --.

Column 2,

Line 4, after "invention" insert --, --.

Column 3.

Line 8, "access" should be -- assess --.

Line 53, "circumstance" should be -- circumstances --.

Column 7,

Line 63, "INTC₁₂" should be -- INTC_{i2} --.

Column 8,

Line 8, "INTC₁₂" should be -- INTC_{i2} --.

Line 12, "INT₁₂ = $\int Ion(t) dt \times PWM_{DC} = \int Ion(\theta) d\theta \times PWM_{DC} / (6 \times RPM)$ " should be

-- INT $_{12} = \int lon(t) dt \times PWM_{DC} = \int lon(\theta) d\theta \times PWM_{DC} / (6 \times RPM)$ --.

Line 18, "INTC $_{12} = \int Ion(\theta) d\theta = 6 \times RPM \times INT_{12} / PWM_{DC}$ " should be

-- INTC $_{i2} = \int Ion(\theta) d\theta = 6 \times RPM \times INT_{i2} / PWM_{DC} -$

Line 20, "INTC₁₂" should be -- INTC_{i2} --.

Column 11,

Line 47, "TH_{PC}" should be -- TH_{FC} --.

Column 12,

Line 1, after "assembly" insert -- threshold THFC, the diagnostic subroutine determines that the ignition coil/ion-sensing assembly --.

Column 15,

Line 23, "PFT" should be -- PFI --.

Line 32, "band" should be -- bank --.

Line 50, "is" should be -- if --.

Column 16,

Line 28, "change" should be -- changes --.

Column 17,

Line 42, "soil" should be -- coil --.

UNITED STATES PATENT AND TRADEMARK OFFICE. **CERTIFICATE OF CORRECTION**

PATENT NO. DATED

: 6,922,628 B2

: July 26, 2005

INVENTOR(S) : Guoming G. Zhu et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 20, Line 14, ";" should be -- : --.

Signed and Sealed this

Eleventh Day of October, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office